PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 791 Date: 23. 12. 2823
It is certified that an inspection team headed by Mr. G. Shri Nagar
(Name of
Officers with designation) from Sub Engineer PHED, Narsinghpur
(Name of Department/Office) inspected the
Daksh International School, Shan Mander
Road, Gadarwada, District Narsinghpur Name & Address
of the School) on 22.12.2023 and found that the Daksh
International School (Name of school) has
safe drinking water facilities for the students and members of staff of the institution
and is maintaining the hygienic sanitation condition in the school building & the
campus as per the norms prescribed by the Central/State/U.T Govt.
The above valid for a period of 1 Year.
Signature with Seal: Suo Division 23:12:2
Name
Designation: Assistant Enginee
Designation: Assistant Enginee PHED, Sub Dn. Narsingu
Young Engl.
Dahsh International School
hadanvada.
(Name & Address of the Institution)