

BUILDING SAFETY CERTIFICATE


No. 817/2023-24

Dated: 13/09/2023

It is certified that the existing building **Daksh International School** (name of the building or premises) at **Amgaon Bada, Kareli, Dist. Narsinghpur** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + First floor					

The building is owned/occupied by **Daksh International School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD PIU Narsinghpur M.P.** (Name of Department/ Govt.) on **13/09/2023** (date of inspection) in the presence of **Mr. Chaitanya Yadav** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **13/09/2023** for a period of **1 year** in accordance with rule.


Divisional Project Engineer
PWD PIU Narsinghpur (M.P.)
PWD PIU Narsinghpur (M.P.)